

FIRMWARE - RELEASE						NO.: SR-801251.04			
General Information: Software-Number: 126720 Last released Version: 2019-04-02 New Version: new versions refer to right side Release Date: 2019-06-24 Software Author: B. Wyss Affected Products: DTS 4801.masterclock V2 DTS 4802.masterclock V2 DTS 4806.masterclock Standard DTS 4806.masterclock Extended Product-Number(s): 203397, 203495, 203782, 123746, 124808				Affected File(s): ProductVersion: - 00020419.01.02020154 dts480xapp.ubifs - dtsapp 124182 V2.03.0000 - timedev 124183 V1.03.0000 - ntp 124186 V4.2.8p10.002 - moba-snmpd 124187 V2.00.0001 - Language0.res V1.12 - Language1.res V1.12 - DTS-COMMON.MIB 201204190000Z - DTS480x.MIB 201906241000Z dts480xcfg.ubifs - timezone table: moba 0010 user 0001 dts480xrootfs.ubifs - RootFS 124185 020419.132534 - Busybox V1.28.4.0000 - snmpd V5.7.3.0000 dts480xu-boot.imx - Bootloader 124188 V2016.11-00004 -1.1.0 dts480xzImage - kernel 124184 V4.9.76.0000 dts480xdevicetree.dtb - devicetree V1.01.0001 dts480xcheck.md5					
Release by Software Developer: This signature validates the release: B. Wyss									
Modifications, Improvements: - NMEA sync search ZDA packet - T1118 increased timeout for P_Time softdog - T1129 line 2 voltage settings not working over SNMP									
Reason for Modification, Impro.: - Customer feedback / internal									
Recommendation for Update:		Action MB Production: Responsible for Action:		See below Name of MB person in charge					
Procedure for Update: See Bx-801250.00 or higher: chapter 7									
Remarks, Enclosures: Vom Entwickler auszufüllen:									
- Prüfsystem kompatibel mit neuer Firmware: <input type="checkbox"/> OK <input checked="" type="checkbox"/> N/A - Neue Firmware in Produktions-Verzeichnis verfügbar: <input type="checkbox"/> OK <input type="checkbox"/> N/A - Updateprozess auf Gerät getestet: <input checked="" type="checkbox"/> OK <input type="checkbox"/> N/A - Versionsanpassung komplettes Gerät nötig?:no <input checked="" type="checkbox"/> OK <input type="checkbox"/> N/A				- Version angepasst: <input checked="" type="checkbox"/> OK <input type="checkbox"/> N/A - Source Code gesichert: <input checked="" type="checkbox"/> OK <input type="checkbox"/> N/A - Dokumentationsanpassung definiert: <input type="checkbox"/> OK <input checked="" type="checkbox"/> N/A					
Distribution PositionE Name Date Signature	<input checked="" type="checkbox"/> E → B. Wyss 24.06.19	<input checked="" type="checkbox"/> EL → HJ. Rohrer 24.06.19	<input checked="" type="checkbox"/> FL → J. Horak	<input checked="" type="checkbox"/> E → B. Wyss	<input checked="" type="checkbox"/> CSO → M. Friedli	<input checked="" type="checkbox"/> FL → J. Horak	<input checked="" type="checkbox"/> E B. Wyss	<input checked="" type="checkbox"/> Filing: A. Kohler	Support → External: <input type="checkbox"/> Verkaufsgesellschaften

Anweisung zu Verteilung und Ablage: Das Dokument wird in der Regel per interne Post (Lauffleiste) an die verschiedenen Stellen gesandt und von jeder Stelle datiert und visiert. Das Dokument wird erst datiert und weitergeleitet, wenn die oben verlangten Aktionen ausgeführt sind. Zur Ablage im DMS und Information der Verkaufsstellen soll das Dokument direkt per E-Mail an den PM gesandt werden.
Vor der Freigabe der Firmware muss die Produktion informiert werden, damit keine Aufträge in Produktion sind und damit die neue Firmware im ERP eingetragen werden kann (erstes FL Feld) gemäss AA-952003 Softwareentwicklung Kap. „Behandlung Firmwares in der Produktion“