

| SR-Release | Internal Version | File name | Product Version | Update instruction | Mandatory step |
|--------------|------------------|---|------------------------|---|----------------|
| SR-800801.06 | 20022015 | DTS 4138 Version 20-02-2015.zip | 03040612.010000.010005 | | |
| SR-800801.07 | 28032018 | DTS_4138_Version_28-03-2018.zip | 04040612.010000.010006 | | |
| SR-800801.08 | 25022019 | DTS_4138_Version_25-02-2019.zip | 05140219.010001.020107 | First step: Update rootfsDTS4138.img, ulmageDTS4138, dts4138app.img image and dtscheck.md5. After reboot update dts4138cfg.img and dtscheck.md5 (save configuration before this update) | |
| SR-800801.09 | 26082020 | 129407_DTS4138_MOBA_V26062020_09_20200826_IMG.zip | 06130220.010001.020308 | First step: Update with dtscheck.md5, rootfsDTS4138.img, ulmageDTS4138 and dts4138app.img image. After reboot, second step: update with dtscheck.md5, dts4138v2cfg.img (save configuration before this update) | x |
| SR-800801.10 | 26102021 | 129407_DTS4138_MOBA_V26102021_10_20211026_IMG.zip | 07251021.010002.020409 | Update 26082020 first | x |
| SR-800801.11 | 29032022 | 129407_DTS4138_MOBA_V29032022_11_20220329_IMG.zip | 07051121.010002.020510 | Update 26102021 first | |
| SR-800801.12 | 28112022 | 129407_DTS4138_MOBA_V28112022_12_20221128_IMG.zip | 07181122.010002.030611 | Internal Version 26102021 or newer must be installed | |
| SR-800801.13 | 29062023 | 129407_DTS4138_MOBA_V29062023_13_20230629_IMG.zip | 07120523.010002.040711 | Internal Version 26102021 or newer must be installed | |
| SR-800801.14 | 19122023 | 129407_DTS4138_MOBA_V19122023_14_20231219_IMG.zip | 07291123.010002.050812 | Internal Version 26102021 or newer must be installed | |
| SR-800801.15 | 13032024 | 129407_DTS4138_MOBA_V13032024_15_20240313_IMG.zip | 08130324.010002.050813 | Internal Version 26102021 or newer must be installed | |