

SR-Release	Internal Version	File name	Product Version	Update instruction	Mandatory step
SR-800801.06	20022015	DTS 4138 Version 20-02-2015.zip	03040612.010000.010005		
SR-800801.07	28032018	DTS_4138_Version_28-03-2018.zip	04040612.010000.010006		
SR-800801.08	25022019	DTS_4138_Version_25-02-2019.zip	05140219.010001.020107	First step: Update rootfsDTS4138.img, ulmageDTS4138, dts4138app.img image and dtscheck.md5. After reboot update dts4138cfg.img and dtscheck.md5 (save configuration before this update)	
SR-800801.09	26082020	129407_DTS4138_MOBA_V26062020_09_20200826_IMG.zip	06130220.010001.020308	<b>First step:</b> Update with dtscheck.md5, rootfsDTS4138.img, ulmageDTS4138 and dts4138app.img image. <b>After reboot, second step:</b> update with dtscheck.md5, dts4138v2cfg.img (save configuration before this update)	x
SR-800801.10	26102021	129407_DTS4138_MOBA_V26102021_10_20211026_IMG.zip	07251021.010002.020409	Update 26082020 first	x
SR-800801.11	29032022	129407_DTS4138_MOBA_V29032022_11_20220329_IMG.zip	07051121.010002.020510	Update 26102021 first	
SR-800801.12	28112022	129407_DTS4138_MOBA_V28112022_12_20221128_IMG.zip	07181122.010002.030611	Internal Version 26102021 or newer must be installed	
SR-800801.13	29062023	129407_DTS4138_MOBA_V29062023_13_20230629_IMG.zip	07120523.010002.040711	Internal Version 26102021 or newer must be installed	
SR-800801.14	19122023	129407_DTS4138_MOBA_V19122023_14_20231219_IMG.zip	07291123.010002.050812	Internal Version 26102021 or newer must be installed	
SR-800801.15	13032024	129407_DTS4138_MOBA_V13032024_15_20240313_IMG.zip	08130324.010002.050813	Internal Version 26102021 or newer must be installed	
SR-800801.16	08072024	129407_DTS4138_MOBA_V08072024_16_20240708_IMG.zip	08050724.010002.050914	Internal Version 26102021 or newer must be installed	
SR-800801.17	19112024	129407_DTS4138_MOBA_V19112024_17_20241119_IMG.zip	08011124.010002.050915	Internal Version 26102021 or newer must be installed	