

FIRMWARE - RELEASE

NO.: SR-801076.03

General Information:

Software-Number: 129764
Last released Version: 26112021
New Version: For new versions see right side
Internal named "Version"
 16022024
Release Date: 20.03.2024
Software Author: hjr
Affected Products: Network Timeserver NTS
 Network Timeserver IT NTS IT
Product-Number(s): 117990 (205650), 118464

Affected File(s):

ProductVersion:
 - 00160224.01.030305
ntsapp.img
 - ntsapp 205520 V1.03.0000
 - timedev 205521 V1.00.0000
 - ntp 205522 V4.2.8p17.003
 - moba-snmpd 205528
 V1.11.0000
 - Language0.res V0.04
 - Language1.res V0.04
 - MOBA-COMMON.MIB
 201301300000Z
 - NTS.MIB 202007221319Z
ntsv2cfg.img
 - timezone table: moba 0010
 user 0001
rootfsNTS.img (205527)
 - Built 160224.114123
 - Busybox 205526 V1.31.1.0002
 - snmpd 205524 V5.8.0.0000
u-bootNTS
 - bootloader 205525 V2012.04
ulmageNTS
 - kernel 205523 V3.2.3.0000

Release by Software Developer:

This signature validates the release: 

Modifications, Improvements:

See CHANGELOG.md

Reason for Modification, Impro.:

-
-

Recommendation for Update:






Stock to be update by production: (AVOR is responsible)

Procedure for Update:

Remarks, Enclosures:

Vom Entwickler auszufüllen:

- | | | | | | |
|---|-------------------------------------|--------------------------|--|-------------------------------------|-------------------------------------|
| - Prüfsystem kompatibel mit neuer Firmware: | <input checked="" type="checkbox"/> | <input type="checkbox"/> | - Versionsanpassung komplettes Gerät nötig?: | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| - Neue Firmware in Produktions-Verzeichnis verfügbar: | <input checked="" type="checkbox"/> | <input type="checkbox"/> | - Version angepasst: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| - FW auf Programmiermedium kopieren (AVOR): | <input checked="" type="checkbox"/> | <input type="checkbox"/> | - Source Code gesichert: | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| - Neue Firmware in Sales-Verzeichnis verfügbar : | <input checked="" type="checkbox"/> | <input type="checkbox"/> | - Dokumentationsanpassung definiert: | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| - Updateprozess auf Gerät getestet: | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |

Distribution	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
PositionE	Entwickler →	EL →	AVOR →	Prüfsystem	Entwickler →	→	→	Ablage:
Name	20.3.24	HJ. Rohrer	M. Schöni	TSi	11.4.24	A. Kohler
Date		22.3.24	2.4.24	11.04.24				
Signature								

Anweisung zu Verteilung und Ablage: Das Dokument wird in der Regel per interne Post (Laufleiste) an die verschiedenen Stellen gesandt und von jeder Stelle datiert und visiert. Das Dokument wird erst datiert und weitergeleitet, wenn die oben verlangten Aktionen ausgeführt sind. Zur Ablage im DMS und Information der Verkaufsstellen soll das Dokument direkt per E-Mail an AK gesandt werden. Die Freigabe der Firmware erfolgt gemäss AA-952003 Softwareentwicklung Kap. „Behandlung von Firmwares“. Dieses Dokument ist nur für internen Gebrauch!